


SpotCell Attic Installations

This bulletin is a reminder that the power supplies and Coverage Units from the SpotCell 100/200 series systems and SpotCell 2500Xe systems should not be located in attics.



A survey of attics in North America showed that temperatures can reach as high as 131°F (55°C). At these temperatures the Coverage Unit and power supply may overheat and sustain damage.

Although the Donor Unit is designed to withstand the high temperatures of enclosed attic spaces, the power supply and Coverage Unit are only rated from 32°F to 104°F (0°C to 40°C).

Do not locate the Coverage Unit or power supply in an attic space.