

## SpotCell 2500Xe Cable Connection

Spotwave Wireless uses premium cable connectors with o-rings in them to seal against environmental effects. With the SpotCell 2500Xe product, the cable connections must be tightened with a wrench in order to compress the o-ring enough to ensure a good connection.

This means that cables need to be tightened (1/4 turn past finger tight) even when temporarily connecting the DU to the CU for system alignment. Failure to properly tighten the connectors may result in an intermittent or broken connection, making it impossible to align the system.

This is not a problem with the earlier Spotwave products (SpotCell 100 and 200 series) as their DU does not have the coaxial pig-tail that is incorporated into the 2500Xe DU.